

To Whom It May Concern,

We have recently received questions about how best to clean and disinfect Stereo Optical vision screener surfaces without damage.

For stereotests and 3-D viewers, clean and disinfect the surface area gently with disinfectant wipes or a soft, slightly damp, and lint-free cloth with 70% isopropryl alcohol. Never spray alcohol directly on the surfaces.

Please feel free to contact us with any questions or for more information.

Best Regards,

Shirley Yin-Piazza, Sr. Marketing Manager

Stereo Optical Co., Inc.

Stilly your Praigy

8600 W. Catalpa Ave., Suite 703

Chicago, IL 60656-1116 Phone: (773) 867-0380 Fax: (773) 867-0388